



United States Steel Corporation Clairton Works 400 State Street Clairton, PA 15025

rmaliveD

DEC 1 0 2012

3AP20

November 29, 2012

Ms. Adina Savage Allegheny County Health Department Department of Air Quality 301 Thirty-Ninth Street Pittsburgh, PA 15201

Subject: USS Reference Number: 12-0344

ACHD Reference Number: N/A "C" Battery Igniter Flare

USS Clairton Works

Dear Adina Savage,

The attached form confirms our verbal report of the subject incident and satisfies the requirements of paragraph IV.8 of ACHD Permit# 0052-I011, as issued on July 24th, 2008.

I certify that based on the information and belief formed after reasonable inquiry, the statements and information in this document are true, accurate, and complete. Any questions concerning this matter should be referred to James Hosfield at 412-233-1015.

Sincerely,

Thomas E. Schumacher Acting Plant Manager

Clairton Works

CC: Ed Peresie (ACHD)

CC: James W. Hagedorn (USEPA)

NOTICE OF OUTAGE OF EQUIPMENT ARTICLE XXI - SECTION 2108.1

1. USS Reference Number: 12-0344 ACHD Reference Number: N/A

- 2. Date & Time of Breakdown: Date: 11/24/12 Time: 1152 hours
- 3. Company Name: U.S. Steel Corporation USS Clairton Works
- 4. Specific Equipment Involved or Affected: "C" Battery Igniter Flare
- 5. BAPC Permit Number (if applicable):input
- 6. Location: Clairton, PA
- 7. Nature and cause of breakdown: Coke oven gas venting occurred on "C" Battery during initial start-up due to a computer input error that stored an incorrect set point for the flare stack.

Date 11/24/12	Battery C	Start Time 11:52	End Time 11:55	Duration		Flared	
				Min. Sec.		Yes	No
				0,2	30	No	

- 8. Identification of Emissions:
 - A. Type(s) (CO, NOX, SO_2 , Particulates, Hydrocarbons, etc.) Raw coke oven gas to atmosphere.
 - B. Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality). Eye, Nose and Throat Irritant.
 - C. Amount of each type emitted (or likely to be emitted).

 Moderate.
- 9. Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so). The flare stack set point was corrected.
- 10. Facility back in operation Date: 11/24/12 Time: 1155 hours

Reviewed by XYY

Environmental Control Engineer Phone: 412-233-1468

Date 2012-11-29